10/ 617640

Practitioner's Docket No. SGL 02/10

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

: US 7,128,963 B2 : Bodo Benitsch

Tssued

: October 31, 2006

Art Unit

: 1775

Examiner

: Archene A. Turner

Title

: Ceramic Composite Body, Method for Fabricating Ceramic

Composite Bodies, and Armor Using Ceramic Composite Bodies

Docket No.

: SGL 02/10

Customer No.

: 24131

Commissioner for Patents

¹ P.O. Box 1450,

Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue

Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.

The Document where the errors are shown correctly in the application file are:

Column 4 line 7, line 15 and line 16 appear correctly in the original application filed on July 10, 2003.

3. Please send the Certificate to:

Name : LERNER GREENBERG STEMER LLP

Address: P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

☐ Assignment recorded on	6)2	Sun
	(name of auth	orized person signing
Reel:	WERNER H. STEMER	
Frame:	REG. NO. 34,956 Attorney	of Record
	litle of authori	ized person signing
☐ Attached is a Recordal of assignr	nent	
Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)" (establishing the right of the assignee to take action in this case)		Certificate
		NOV 2 8 2006
Date: Nov. 20, 2006		of Correction

of Correction

Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

US 7,128,963 B2

Page 1 of 1

APPLICATION NO

10/617,640

DATED

October 31, 2006

INVENTOR(S)

Bodo Benitsch

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 7, "750 m." should read -- 750 μm. --.

Line 15, "50 m" should read -- 50 μm --.

Line 16, "50 m" should read -- 50 μ m ---

MAILING ADDRESS OF SENDER:

PATENT NO. 7,128,963

Lerner Greenberg Stemer LLP P.O. Box 2480 Hollywood, FL 33020

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

US 7,128,963 B2

Page 1 of 1

APPLICATION NO

10/617,640

DATED

October 31, 2006

INVENTOR(S)

Bodo Benitsch

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 7, "750 m." should read -- 750 μm. --.

Line 15, "50 m" should read -- 50 μm --.

Line 16, "50 m" should read -- 50 μm --.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,128,963

Lerner Greenberg Stemer LLP P.O. Box 2480 Hollywood, FL 33020

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.